

SERVICE INFORMATION CRUISE CONTROL

MS901 Boxer Pedal track fault

Reason of information:

Date: 18-07-2013

In combination with after market cruise control unit, car ECU will periodically produce a fault message P2138 in the diagnostic message system. This information is valid **only** to vehicles who is affected to the symptom.

Fault appears:

Limping mode become active. DTC codes are generated.

Reason of fault:

Bad connection between terminals and wire crimps inside the moulding connector (pedal interface) generate too high resistance.

Solution:

Change out the existing main wire with new type part no. DC-CC-OE-28A or DC-CC-OE-21AX.

Note:

This information substitute all earlier service information regarding *Pedal track fault*.

