Troubleshooting i30 Cruise Control part no. E9600 2L020

Fault describtion

Cruise control dosnt work after quick on/off ignition key (less than 15 sec between).

Reason

Cruise control make internal shutdown and must be reset. This is normal by having ignition *off*, more than 15 sec.

Solution

Move current power line from brake curcuit onto +15 fuseline.

