Instruction		GB	
Model	Sportage II w/o ESP	Type of model	CRDI
		Description	Cruise control
		Part number	E9600 66012A
		Manufacturer	Dancar Autosikring
Production	26/06/07	Installation time	30 min.




The product which is described in the guide was developed, produced and inspected as regards the necessary security precautions.


In order to guarantee a faultless operation and thus exclude the dange


In order to guarantee a faultless operation and thus exclude the danger to people and objects, this product must be mounted in accordance with professional guidelines.


Internal fitting must thus only be performed by professionals who possess the necessary technical knowledge and the necessary tools. The mounting guide must be read thoroughly.

Before starting the mounting you must make sure that the mounting kit is complete.













JKH026GB V1 26/6-07


Copyright: dancar

















Page 3/4

<b>B</b> I	_		-0
N	O	ΙĖ	-5

CAR-PROGRAM LIST		DANCAN TOO		USABLE CONTROL UNIT			
		DANCIAN 1000  Vanisse Call of the State of t		SET -	SET -	Too O	
Car model	Year		Remark	Program no:	E9698-66050	E9698-66051	E9698-66000
SPORTAGE KM	25/8 2004-		W/O ESP	2	Yes		Yes

Updated fitting instruction and carlist see: